# Laser Scanning

Capture. Analyze. Define.

# The Technology



Capture. Analyze. Define

Benefits of laser scanning

Fast: Collects millions of data points per minute

- Accurate: Scan data is extremely accurate due to the amount of data collected
- Safe: Non-contact measurement tool used from the ground and away from hazards
- Cost-effective: Able to collect more valuable data in less time, with little or no re-visits creating greater cost savings




# The Technology

Capture. Analyze. Define.

Two type of 3D laser scanners

- © LIDAR (Laser Imaging, Detection & Ranging)
- Phase-based





# The Equipment

Capture. Analyze. Define.

## Leica C-10 ScanStation

- © Uses LIDAR
- Fast Scans 50,000 data points/second
- Accurate to within 2mm-4mm up to 300m
- © Limited to Line of Sight
- © Capable of taking photographs
- Able to be used in wide range of applications







#### Leica P-20 ScanStation

- © Uses LIDAR & Phase-based
- Fast Scans 1,000,000 data points/second
- Accurate to within 2mm-4mm up to 120m
- © Limited to Line of Sight
- © Capable of taking photographs
- Able to be used in wide range of applications





# **Equipment Applications**

Capture. Analyze. Define

© "As-builts" ©New construction "verifications" © Prefabrication ©Clash Detection © Historical Preservation © Overhead Clearance Verification © Volume Calculations © Telecommunication & Transmission Towers




Capture. Analyze. Define.

- © Point Cloud data Raw Data
- © TruView Free viewer w/ photos overlaid on point cloud
- © "Fly-thru's" 3D virtual tour of point cloud or model
- © 2D & 3D CAD drawings
- © 3D BIM models
- © Other customizable options upon request



Capture. Analyze. Define.






Capture. Analyze. Define.

#### TruView - Photo documentation from Scanner






Capture. Analyze. Define.





Capture. Analyze. Define.

#### 2D Drawings & Floor Plans





Capture. Analyze. Define.


## **2D Elevations**





# **Applications - Measurements**


Capture. Analyze. Define.





## **Applications - Measurements**

Capture. Analyze. Define.





## **Applications - Measurements**

Capture. Analyze. Define

#### **Overhead Line Clearances**

According to OSHA, 30% of all electrical-related fatalities involved overhead power lines <u>www.osha.gov</u>

Approach A

14.620 0

# Applications



Capture. Analyze. Define.

#### **Clash Detection**


Interference Report
Group by: Category 2, Category 1 🔻
Message
Mechanical Equipment
- Floors
- Floors : Floor : 3 1/4" Concrete on 3" Metal Deck : id 285231
Mechanical Equipment : Shaft Block : Shaft Block : id 356058   Floors
Floors : Floor : 3 1/4" Concrete on 3" Metal Deck : id 285287
Mechanical Equipment : Shaft Block : Shaft Block : id 356058
- Floors
Floors : Floor : 3 1/4" Concrete on 3" Metal Deck : id 285343
Mechanical Equipment : Shaft Block : Shaft Block : id 356058
Floors
Floors : Floor : 3 1/4" Concrete on 3" Metal Deck : id 296541
Mechanical Equipment : Shaft Block : Shaft Block : id 356058   Floors
Floors : Floor : 3 1/4" Concrete on 3" Metal Deck : id 211126
Mechanical Equipment : Shaft Block : Shaft Block : id 356058
*
*
Created Catendary Jacours 05, 2012 0-20-07 DM
Created: Saturday, January 05, 2013 9:38:07 PM
Last Update:
Note: Refresh updates interferences listed
Show Export, Refresh Close



# Applications

Capture. Analyze. Define.

## **Clash Detection**





# Applications


Capture. Analyze. Define.

## **Contours of Floor Surfaces**






Capture. Analyze. Define.





Capture. Analyze. Define.

## Going from point cloud to model





# Deliverables: From Scan to Model

Prep and Referencing the Point Cloud

- A raw cloud format file is created and exported from the laser scanning software.
- This raw cloud file is "indexed" (by Recap, AutoCAD or Revit) into a file to be used as an external reference.
  - © Indexing file times vary with raw file size.
  - © 7.5 gigabyte over 2 hours to index.
  - © Some clouds index over a weekend.



Capture, Analyze, Define

# Deliverables: From Scan to Model


Steps to create design documents

- © Index Raw Point Cloud File(s).
- © Point Cloud is attached to design file.
- © Scale and units are verified.
- © Clip cloud to area of interest.
- © Trace cloud (2D or 3D)



Capture. Analyze. Define.


Using the point cloud, drawings and plans were created using highly accurate asbuilts, avoiding costly mistakes and reducing planning phase by an estimated 3 weeks.





Capture. Analyze. Define.


## Fly-thru of Hotel model





Capture. Analyze. Define.


## Revit Model of Airport TSA Security Checkpoints





Capture. Analyze. Define.


## 3D CAD Model – Front View of Residence





Capture. Analyze. Define.


## 3D CAD Model – Back View of Residence





Capture. Analyze. Define.

## 3D CAD Model – Masonry Detail of Residence







Capture. Analyze. Define.


#### 3D Wireframe of Exterior of Church





Capture. Analyze. Define.

## 3D Axonometric View of Church





Capture. Analyze. Define.


#### Key Plan with Google Maps overlay





Capture. Analyze. Define.

## 3D CAD Model - Overview





Capture. Analyze. Define.


## 3D CAD Model – Overview (Zoomed In)





Capture. Analyze. Define.


## 3D CAD Model – Close Up





Capture. Analyze. Define.

## 3D BIM Model of Structure & MEP





# **Notable Projects**

Capture. Analyze. Define.

Hyatt Regency – Chicago, IL.







Capture. Analyze. Define.

## Ohio State University Medical Center Mechanical Room – Columbus, OH.





Capture. Analyze. Define.


### Marathon Petroleum Company – Cincinnati, OH.





Capture. Analyze. Define.


### University of Michigan – Ann Arbor, MI.





Capture. Analyze. Define.

### DTE Energy – Detroit, MI.







Capture. Analyze. Define.





Capture. Analyze. Define.





Capture. Analyze. Define.






Capture. Analyze. Define.






Capture. Analyze. Define.





Capture. Analyze. Define.


#### Carmeuse Lime & Stone





Capture. Analyze. Define.


### **BP** Pipeline








Capture. Analyze. Define.





Capture. Analyze. Define.

### Bridger Power Plant – Rock Springs, Wyoming





Capture. Analyze. Define.

### Arcadis – Elgin MGP Substation






Capture. Analyze. Define.

# Hollywood Casino – Columbus, Ohio TAKE GRIL



Capture. Analyze. Define.


Cobo Hall Arena - Detroit, MI.





Capture. Analyze. Define.

### Kenwood Multipurpose Tower – Cincinnati, OH





Capture. Analyze. Define.


### 600 Canal Street – New Orleans, LA





Capture. Analyze. Define.

### Ohio Department of Transportation & University of Toledo – Toledo, OH.








Capture. Analyze. Define.


### Norton-Brownsboro Hospital – Louisville, KY.






Capture. Analyze. Define.

### Norton-Brownsboro Hospital – Louisville, KY.








Capture. Analyze. Define.


### Cincinnati Children's Hospital – Cincinnati, OH





Capture. Analyze. Define.

### Cincinnati Children's Hospital – Cincinnati, OH





Capture. Analyze. Define.

### Wayne County Courthouse





### **Benefits for Projects**

Capture. Analyze. Define

© Limit Change Orders © Typically 3-5% project cost in change orders © 1/3 Owner Requested © 1/3 Errors and Omissions © 1/3 Field Conditions © Limit E/O and Field **Conditions Change Orders** © More info for design teams early = better design





### How to best see value

Capture. Analyze. Define

 Contract Directly
 Most Value and control for owner
 Add Laser Scanners to Project Team
 Owners ultimately pay for scanning plus markup
 Suggest Project Team use Laser Scanning
 Owners ultimately pay for scanning plus markup
 Owners ultimately pay for scanning plus markup
 Owners expose themselves to Field Condition Change Order Costs



### **Contact Information**

Capture. Analyze. Define.

TruePoint Laser Scanning, LLC. 6800 W. Central Avenue, Suite E-1 Toledo, Ohio 43617 419-843-SCAN (7226)

www.TruePointScanning.com

Ryan Hacker rhacker@truepointscanning.com

Ann Arbor/Detroit – 734-807-0117 Chicago – 312-448-1509 Cincinnati – 513-609-7244 Cleveland – 216-470-7262 Columbus – 614-800-0378 Dallas, TX. – 214-551-6201 Indianapolis, IN. - 317-560-1565 Orlando, FL. – 407-558-9716 Pittsburgh – 412-639-7564 Washington D.C. – 703-517-5773